

Kernel

make-command

- <https://github.com/BPI-SINOVOIP/BPI-R64-bsp>
- 4.19 / 5.4-rc
 - both switches working, currently no dsa-driver available
 - bluetooth untested (was working in 4.19)
 - no wifi driver available

debug

```
dev_info(gsw->dev, "%s:%d 0x%x", __FUNCTION__, __LINE__, val);  
printk(KERN_ALERT "DEBUG: Passed %s %d \n", __FUNCTION__, __LINE__);
```

```
#define onlinedbg(dev, fmt, ...) {if (dev) dev_info(dev, "%s:%d " "  
fmt, __FUNCTION__, __LINE__, ##__VA_ARGS__);else printk(KERN_INFO "%s:%d " "  
fmt, __FUNCTION__, __LINE__, ##__VA_ARGS__);}
```

makefile:

```
$(info $$var is [${var}])
```

From:

<http://www.fw-web.de/dokuwiki/> - **FW-WEB -Wiki**

Permanent link:

<http://www.fw-web.de/dokuwiki/doku.php?id=en:bpi-r64:kernel>

Last update: **2020/08/29 17:14**

